



Radon in Air

NEHA NRPP 101021

Property Tested

EPA Method #402-R-93-004
NEHA Device Code 8088

Laboratory Report For

3 Erins Way
Hamilton MA 01982

Log Number	Device Number	Area Tested	Result (pCi/L)
750774	1642432	Basement	2.4
750775	1642433	Basement	2.8
			Average: 2.6

Radon test results are below the EPA action level of 4 pCi/L. No further action is required at this time. The EPA suggests that you may want to test again in the future to insure that radon levels remain below the action level.

Radon measurement performed by: Bedrock Building Inspection Service

Test Began: 5/3/2006 10:30 AM

Date Received: 5/9/2006

Test Ended: 5/5/2006 10:35 AM

Date Analyzed: 5/9/2006

Test Device(s) were open 2.00 days

Date Reported: 5/10/2006

Report Reviewed By: *Copy for file. Original report has been mailed to the address above.*

Disclaimer: The uncertainty of this radon measurement is $\sim\pm 10\%$. Factors contributing to uncertainty include, statistical variations, daily and seasonal variations in radon concentrations, and operation of the dwelling. Interference with test conditions may influence the test results.

This report may only be transferred to a third party in its entirety. Results shown on this report represent levels of radon gas measured between the dates shown in the room or area of the site identified above as "Property Tested". Incorrect information will affect results. The results may not be construed as either predictive or supportive of measurements conducted in any area of this structure at any other time. AccuStar Labs, its employees and agents are not responsible for the consequences of any action taken or not taken based upon the results reported or any verbal or written interpretation of the results.

Page 1 of 1

3 Saber Way Ward Hill MA 01835 888-480-8812 978-521-2163